




















M311




№		PCS	 mm	 mm	 mm
1		2	19	52	2000
2		1	19	46	2000
3		23	19	92	2000
4		4	OSB	35	1000
5		44	19	92	1300
6		2	19	92	1300
7		1	48	84	1290
8K		1	38	38	1842
8D		1	38	38	1842
9		2	OSB	800	1400
9.1		1	OSB	400	1400
10		2	13	92	1413
11		4	15	35	1800
12		1	13	92	2000
13		4	15	35	1350
14		1		585	1760
15		1		585	1760
16		2	15	35	855
17		42	19	92	384
18		1	15	69	1180
19		3	15	35	666
20		2	18	50	1147
21		2		1000	1500
22		1		500	1500
23		6			
24		3			
25		1			

1




№	PCS	DIMENSIONS		
1	8	25	30	200
2	2	38	38	1880
3	6	38	38	1104
4	14	19	92	1880
A	12	 M4x70		
B	84			
C	32	 M4x45		






2




C x32




1



1



2



3

Int.

7
 C_{x4}

8

6

2

6

3


18

C_{x5}

Int.


B_{x12}

Ext.




4


Int.



Int.





Ext.



D_x4


11






A_x2

C_x8

Int.



5



6

Int.

C x8
24

16

25


24

16




C x14

Int.


Ext.




7



8



9



10

